



10/600,568

GJC

PATENT  
Customer No. 22,852  
Attorney Docket No. 4329.2444-01

**IN THE UNITED STATES PATENT AND TRADEMARK OFFICE**

In re U.S. Patent No.: 6,897,143 B2 )  
Inventors: HIROSHI TOYODA ET AL. )  
Issue Date.: May 24, 2005 )  
For: METHOD OF MANUFACTURING )  
SEMICONDUCTOR DEVICE )  
INCLUDING TWO-STEP )  
POLISHING OPERATION FOR CAP )  
METAL )

Certificate  
JUN 23 2005  
of Correction

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

Sir:

**REQUEST FOR CERTIFICATE OF CORRECTION**

Pursuant to 35 U.S.C. § 254, and 37 C.F.R. § 1.322, this is a request for a Certificate of Correction in the above-identified patent. The mistake identified in the appended Form occurred through the fault of the Patent Office, as clearly disclosed by the records of the application which matured into this patent.

Two (2) copies of PTO Form 1050 are appended. The complete Certificate of Correction involves one (1) page. Issuance of the Certificate of Correction containing the correction is earnestly requested.

JUN 24 2005

Please charge any required fees not included herewith to our deposit account


06-0916.

Respectfully submitted,

FINNEGAN, HENDERSON, FARABOW,  
GARRETT & DUNNER, L.L.P.

Dated: 6/17/05

By:

  
Richard V. Burgulian  
Reg. No. 31744

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. 6,897,143 B2

DATED: May 24, 2005

INVENTORS: Toyoda et al.

It is hereby certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Claim 12, column 14, line 44, change "bonde" to --boride--.

MAILING ADDRESS OF SENDER

Patent No. 6,897,143 B2

Finnegan, Henderson, Farabow,  
Garrett & Dunner, L.L.P.  
901 New York Avenue, N.W.  
Washington, D.C. 20001-4413

No. of additional copies  
@ .30¢ per page

JUN 24 2005